SECTION AL-MESIC	h Hazard Data			
Routes of Entry ->	Inhalation? YES	Skii YE		Ingestion? UNLIKELY
Health Hazards (Acute and			<u> </u>	ONLINELI
	ciant. May reduce oxy	aen required for bre	athing. Liquid	gas may freeze ski
Carcinogenicity ->	NTP?	IARC Mon		OSHA Regulated?
	N/A	N/.	Α	NO
Signs and Symptoms of Exp Dizziness to u	osure nconsciousness if h	igh concentrations o	f gas replace o	oxygen for breathin
Medical Conditions General	lly Aggravated by Exposure N/A			
Emergency and First Aid Pr	rocedures			
		to fresh air. If uncon	scious, seek r	nedical attention.
Warning				
	,	yproducts of combus		
		n to the State of Cali		e cancer, birth
	•	er reproductive harn	n.	
	autions for Safe Handl	ing and Use		
Steps to be Taken in Case M	laterial is Released or Shilled			
	-	ition sources. Ventila	ate area.	
Waste Disposal Method	Remove all ign Vent to atmosp	ition sources. Ventila		rces of ignition.
Waste Disposal Method	Remove all ign Vent to atmosp	here in outdoor area	free of all sou	
Waste Disposal Method	Remove all ign Vent to atmosp Handling and Storing Store in well ve	phere in outdoor area	free of all sou	sources.
Waste Disposal Method	Remove all ign Vent to atmosp Handling and Storing Store in well ve	here in outdoor area	free of all sou	sources.
Waste Disposal Method Precautions to be Taken in 1	Remove all ign Vent to atmosp Handling and Storing Store in well ve	phere in outdoor area	free of all sou	sources.
Waste Disposal Method Precautions to be Taken in I Other Precautions	Remove all ign Vent to atmosp Handling and Storing Store in well ve Store at tempe N/A	phere in outdoor area	free of all sou	sources.
Waste Disposal Method Precautions to be Taken in 1	Remove all ign Vent to atmosp Handling and Storing Store in well venture at tempe N/A ntrol Measures ecify Type)	phere in outdoor area entilated area away fr ratures below 125° F	free of all sou	sources.
Waste Disposal Method Precautions to be Taken in l Other Precautions SECTION VIII - Correspiratory Protection (Spe	Remove all ign Vent to atmosp Handling and Storing Store in well ventore at tempe N/A ntrol Measures perify Type) Not required w	chere in outdoor area entilated area away fr ratures below 125° F	free of all source. Store out of c	sources. lirect sunlight.
Waste Disposal Method Precautions to be Taken in l Other Precautions SECTION VIII - Correspiratory Protection (Spe	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A ntrol Measures cify Type) Not required w Local Exhaust	chere in outdoor area entilated area away fr ratures below 125° F.	free of all source of all source of contact	i sources. lirect sunlight.
Waste Disposal Method Precautions to be Taken in 1 Other Precautions SECTION VIII - Correspondence (Special Control of Special Control of Speci	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A ntrol Measures ecify Type) Not required well to the store at tempe Local Exhaust Advisable when	chere in outdoor area entilated area away fr ratures below 125° F	free of all source. Store out of c	sources. lirect sunlight.
Waste Disposal Method Precautions to be Taken in 1 Other Precautions SECTION VIII - Co. Respiratory Protection (Special Special S	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A ntrol Measures cify Type) Not required w Local Exhaust	entilated area away fratures below 125° F	free of all source of all source of contact	i sources. lirect sunlight.
Waste Disposal Method Precautions to be Taken in 1 Other Precautions SECTION VIII - Co. Respiratory Protection (Special Special S	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A Introl Measures Perify Type) Not required well to the store at tempe Local Exhaust Advisable when welding.	entilated area away fratures below 125° F	rom all ignition. Store out of c	i sources. lirect sunlight.
Waste Disposal Method Precautions to be Taken in 1 Other Precautions SECTION VIII - Co. Respiratory Protection (Specific Specific Speci	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A Introl Measures Excify Type) Not required well Exhaust Advisable when welding.	entilated area away fratures below 125° F	rom all ignition. Store out of c	osources. Iirect sunlight. Other N/A
Waste Disposal Method Precautions to be Taken in 1 Other Precautions SECTION VIII - Co. Respiratory Protection (Specific Clothing on N/A	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A Introl Measures Excify Type) Not required well Exhaust Advisable when welding.	entilated area away fratures below 125° F	rom all ignition. Store out of c	osources. Iirect sunlight. Other N/A
Waste Disposal Method Precautions to be Taken in I Other Precautions SECTION VIII - Co Respiratory Protection (Specific Specific Spec	Remove all ign Vent to atmosp Handling and Storing Store in well vere at tempe N/A Introl Measures Exify Type) Not required wellocal Exhaust Advisable when welding. Die when welding. The Equipment	entilated area away fratures below 125° F. ith normal use. Mechanical (General) N/A Eye Protection Use filter sh	rom all ignition. Store out of c	osources. Iirect sunlight. Other N/A
Waste Disposal Method Precautions to be Taken in I Other Precautions SECTION VIII - Co Respiratory Protection (Specific Specific Spec	Remove all ign Vent to atmosp Handling and Storing Store in well vents at tempe N/A Introl Measures Poily Type) Not required well Exhaust Advisable when welding. Pole when welding. Por Equipment	entilated area away fratures below 125° F. ith normal use. Mechanical (General) N/A Eye Protection Use filter sh	Special N/A	osources. Iirect sunlight. Other N/A